

Grindmaster PIC Part Reference Guide



61243
Dump Valve Grommet



61523
Whipper Base Assy.



61618
Auger Motor



62937
Circle Light Bulb and Fixture



63195
Sealed Dispense Switch



63496
Red Lamp 125 volt



100090
Gearbox (pic 4)




61131
Heater Relay



61116-01
Whipper Motor



61102
Dump Valve



61103
Fan Motor



61104
Inlet Valve



61118
Light Bulb



61128
Thermistor Probe



61222
Hopper



61229
Plug



61365
Dump Valve O-Ring



61237
Inlet Adapter



61221
Mixing Funnel



61226
Funnel Quick Disconnect



61223
Elbow



61334
Slinger Washer



61461
Angled Restrictor Button



61372
Hopper Assy.



62921
Pic 5 Drip Pan Grid



62545
Pic 4 Drip Pan Grid



61617
Pic 1 Drip Pan Grid



62922
Pic 6 Drip Pan Grid



62335
Drip Pan Lowered




62866
Drip Pan Pic 6



62833
Drip Pan Pic 5



63165
Drip Pan Pic4



61227
Tank Lid Gasket



61255
Steam Shroud



61315
Hopper Lid



61847
Power Switch



62395
Whipper Camber



63495
Green Lamp



62639
5.5 LB Hopper Assy.



62640
11 LB. Hopper Assy.



100549
300 degree Elbow



61459
Whipper Base Seal



61127
Funnel O-ring



07327
Clamp



63454
240 Degree Elbow



61458
Whipper Blade